Common Sparky Commands

- ol—overlay spectra
- ct—adjust contour levels
- rp—read peak list
- pc—center peaks
- lt—peak list (update regularly and save lists here)
- hI—access comprehensive command index